




Invoice




SOLD TO:



MINDEN, NV 89423
 United States

SHIP TO:



United States

CUSTOMER NO: 71-RUSS023
 INVOICE NO: 0905438-IN
 INVOICE DATE: 9/8/2016
 PAGE NO: 1

| CUSTOMER P.O. | ORDER NO | ORDER DATE | SALESPERSON |
|---------------|----------|-------------------------|----------------|
| 37927 | 0630136 | 9/8/2016 | WEB |
| TELEPHONE NO. | FAX NO. | SHIP VIA | PAYMENT METHOD |
| | | FEDX GROUND RG ES AJ BR | MC/V 0526 |

| ITEM NUMBER | DESCRIPTION | ORDERED | SHIPPED | BACK ORDERED | UNIT PRICE | TOTAL |
|-------------|--|---------|---------|--------------|------------|--------|
| | CUSTOMER ADDED QTY 1 EACH OF B3131A AND B3280A . CHARGE ADDED PARTS TO CARD BALANCE PREPAID ON PAYPA | | | | | |
| B 3131A | TIE ROD 61/66 RH/LH OUTER | 2.00 | 2.00 | 0.00 | 49.92 | 99.84 |
| B 3280A | TIE ROD 61/64 RH LH INNER | 2.00 | 2.00 | 0.00 | 49.95 | 99.90 |
| B 3050A | LOWER BALL JOINT 61/66 RH | 1.00 | 1.00 | 0.00 | 59.95 | 59.95 |
| B 3050B | LOWER BALL JOINT 61/66 LH | 1.00 | 1.00 | 0.00 | 59.95 | 59.95 |
| B 3049C | UPPER BALL JOINT 63/66 RH LH | 2.00 | 2.00 | 0.00 | 59.95 | 119.90 |
| | PLEASE SEE PARTSMAN CONCERNING ANY BACK ORDERED PARTS. THANK YOU FOR YOUR ORDER ***** | | | | | |

Thank You!

Guarantee: All new reproduced products are guaranteed against defects in workmanship and materials. **Liability of Larry's Thunderbird & Mustang Parts is limited to the replacement of defective parts.** If you are not satisfied with a purchase and wish to make an exchange or return for refund, we ask that this be done within 30 days of purchase. If it is our error, we will reimburse you for shipping costs. However, all parts must be returned prepaid, via least expensive transportation. Returns will not be accepted on the following items: electrical parts, books, or items with which installation has been attempted. All returns must have a copy of the invoice and may be subject to a restocking charge.

Merchandise Damaged and / or Shorted: Inspect your parts immediately upon receipt. If you should receive parts that are damaged and/or missing due to a broken box, contact the carrier (i.e. FED EX, UPS, DHL, Post Office, or freight lines). They will process your claim. If you find a shortage in your order, you must advise us of that shortage within 7 days. We will only accept responsibility for shortages reported within 7 days. Do not ship the parts back to us! We will do everything we can to see that your claim is taken care of as quickly as possible.

| | |
|-----------------|--------|
| NET INVOICE | 439.54 |
| DISCOUNT | 0.00 |
| SALES TAX | 0.00 |
| FREIGHT | 20.32 |
| INVOICE TOTAL | 459.86 |
| LESS DEPOSIT | 99.87 |
| INVOICE BALANCE | 359.99 |



| PACKAGE ID NUMBER | DATE |
|-------------------|-----------|
| 233017 | 9/15/2016 |

89423

08053



AN 'NEGENTIM' MINDEN, NV

REFER TO THIS NUMBER IN ALL CORRESPONDENCE

| CUSTOMER ORDER NUMBER | TRANSACTION NUMBER |
|-----------------------|--------------------|
| 22705101 | 1634805 |

| QTY. ORDERED | QTY. SHIPPED | PART NUMBER | MANUFACTURER | PART DESCRIPTION |
|-----------------|-----------------|-------------|--------------|-------------------------|
| 1 | 1 | 12760 | EDELBROCK | HDO REBUILD HOLLEY 4150 |

HDQ REBUILD HOLLEY 4150

EDLBRCK

12760

1

1

PAC

Performance Auto Care

PERFORMANCE AUTO CARE, CORP.

4520 OAK STREET

CARSON CITY, NV 89701-6641

PHONE: 775-883-3190

FAX: 775-883-3127

performanceautocare7@gmail.com

www.PerformanceAutoCareNV.com

INVOICE

11/2/2015

49869

MINIDEN NV 89423

Year/Make: 63 FORD

Model: T-BIRD

Odometer: 83,816

LIC: 667 LXF

| ITEM | DESCRIPTION | QUANTITY | RATE | TOTAL |
|-------|--|----------|--------|---------|
| | EST# 22498 VIN# 3Y83Z103382 MECH DAVE + ED | | | |
| LABOR | CHECK VAPOR LOCKS WHEN OUTSIDE TEMP ABOVE 80 | 0.5 | 85.00 | 42.50 |
| | CHECK ENGINE VIBRATION | | | |
| | CHECK AND REC ELECTRIC FUEL PUMP | | | |
| | FOUND NEEDS ACC PUMP IN CARB AND FAN CLUTCH IS BAD | | | |
| LABOR | INSTALL ELECTRIC FUEL PUMP | 1.5 | 85.00 | 127.50 |
| PARTS | FUEL PUMP 610-1075 | 1 | 244.00 | 244.00T |
| PARTS | MISC ELECTRICAL AND INLINE FUSE | 1 | 10.00 | 10.00T |
| LABOR | REPLACE CARB ACCELERATOR PUMP | 1 | 85.00 | 85.00 |
| PARTS | ACCEL PUMP 2-4295 | 1 | 16.27 | 16.27T |
| LABOR | REPLACE FAN CLUTCH | 0.5 | 85.00 | 42.50 |
| PARTS | FAN CLUTCH | 1 | 128.00 | 128.00T |

pd
OK
[Signature]

RECOMMENDED SERVICE

All bad checks will be subject to bank service charges, interest, and prosecution.

I hereby authorize the repair work above to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck, boat, or vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanics lein is hereby acknowledged on above car, truck, boat, or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident, or any other case beyond your control.

Signature:

| | |
|------------------|----------|
| Subtotal | \$695.77 |
| Sales Tax (7.6%) | \$30.27 |
| Total | \$726.04 |
| Payments/Credits | \$0.00 |
| Balance Due | \$726.04 |

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Carson Valley Transmission, Inc.

P.O. Box 2615
Minden, NV 89423
(775) 782-9552

Invoice # 19960

1963 Ford Thunderbird Base

VIN: 3Y832103382

Engine: 352

Trans: MEDIUM CASE CRUISE

License # 667LXF

ODO In:83717 Out: 83732

Color: Blue

Mfg. Date:

Unit #

Inv Date: 8/13/2015

Service Writer: Brenda Murray

Status: Complete

Driver:

PO #

Mobile

| Vehicle Problems | Requests for Service | Services Performed | Hrs | Qty | Price | Ext |
|--|----------------------|-----------------------|------|-------|--------|--------|
| Notes: Won't go into third gear. | | | | | | |
| Labor Service - Remove transmission. Install repaired transmission. renew fluid and road test. KEM | | | 5.00 | | 95.00 | 475.00 |
| New | FLUID 1 | Automatic trans fluid | | 12.00 | 3.12 | 37.44 |
| Labor Service - Disassemble and inspect transmission on bench. Reseal unit complete with all parts listed. KEM | | | 6.00 | | 95.00 | 570.00 |
| New | OHKIT | Overhaul kit | | 1.00 | 112.50 | 112.50 |
| New | ST | Steel | | 1.00 | 9.00 | 9.00 |
| New | ST | Steel | | 4.00 | 2.25 | 9.00 |
| New | ST | Steel | | 6.00 | 9.00 | 54.00 |
| New | PP | Pressure plate | | 1.00 | 15.00 | 15.00 |
| New | CBSH | Case bushing | | 1.00 | 30.00 | 30.00 |
| New | IPB | Input Bushing | | 1.00 | 7.50 | 7.50 |
| New | PB | Pump Bushing | | 1.00 | 10.50 | 10.50 |
| New | FR | Freight | | 1.00 | 35.00 | 35.00 |
| New | F2B | Torque Converter | | 1.00 | 138.00 | 138.00 |
| New | C2SZ-6068-A | Transmission Mount | | 1.00 | 0.00 | 0.00 |
| New | SK | Shift kit | | 1.00 | 50.00 | 50.00 |
| Labor Service - Fuel KEM | | | 1.00 | | 20.04 | 20.04 |

PAID CR # 10301

Warranty

Invoice Summary

| | |
|---------------|----------|
| Parts | 507.94 |
| Labor | 1,065.04 |
| Supply Charge | 15.00 |

X

Customer acknowledges receipt of merchandise and services.

| | |
|-----------------|----------|
| Sub Total | 1,587.98 |
| Sales Tax (DEF) | 37.13 |

I hereby authorize the repair work listed herein, including sublet work, to be done along with necessary materials. You and your employees may operate the described vehicle for the purposes of testing, inspection or delivery at my risk. An express lien is acknowledged on said vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control. Customer agrees to pay all collection costs and /or attorneys fees in the event that default is made in any payment due. If vehicle is returned to customer without repair service being performed, a diagnostic and handling fee (including reassembly) may be charged. I have read and understand the above and acknowledge receipt of an estimate.

X

Terms: CASH unless arrangements made prior to authorization. Vehicles left after repair is completed may be subject to a storage fee.

Carson Valley Transmission, Inc.

P.O. Box 2615
Minden, NV 89423
(775) 782-9552

Invoice # 19651

1963 Ford Thunderbird Base

License # 667LXF

Inv Date: 5/26/2015

ODO In:83505 Out: 83506

VIN: 3Y832103382

Color: Blue

Service Writer: Brenda Murray

Engine: 352

Mfg. Date:

Status: Posted

Mobile

Trans: MEDIUM CASE CRUISE

Unit #

Driver:

PO #

| Vehicle Problems | Requests for Service | Services Performed | Hrs | Qty | Price | Ext |
|---|----------------------|-----------------------|------|------|-------|--------|
| Notes: Check linkage. Won't hold park. | | | | | | |
| Labor Service - Replace motor mounts. KEM | | | 3.00 | | 95.00 | 285.00 |
| New | C1MM-6038-C | Motor Mount | | 2.00 | 24.95 | 49.90 |
| New | FR | Freight | | 1.00 | 10.00 | 10.00 |
| New | 1515 | Oil filter | | 1.00 | 0.00 | 0.00 |
| New | 75-100 | 10w40 motor oil | | 2.00 | 3.89 | 7.78 |
| New | FLUID 1 | Automatic trans fluid | | 1.00 | 3.12 | 3.12 |

Notes


Exhaust pipe touching bell housing. Needs plug wires.

| | | | | |
|--|--|-------------------|--------------------|--------|
| Warranty | Posted 5/27/15 1:32PM Check (10285) | 366.18 | Invoice Summary | |
| | | | Parts | 70.80 |
| | | | Labor | 285.00 |
| | | | Supply Charge | 5.00 |
| | | | | |
| | | | | |
| | | | | |
| X | | | Sub Total | 360.80 |
| | | | Sales Tax (DEF) | 5.38 |
| Customer acknowledges receipt of merchandise and services. | | | | |
| Page 1 of 1 | | Discard old parts | Original Estimate: | 366.18 |
| | | | Total | 366.18 |

X

Customer acknowledges receipt of merchandise and services.

PROFESSIONAL CAR
CARE ANYWHERE



WILLY MACQUELIN
P. O. BOX 6026
GARDNERVILLE, NV 89460

781-1151

REPAIR ORDER

| ★ CODE N-NEW U-USED R-REBUILT | | | |
|-------------------------------|----------|-------------|-------|
| QUAN. | PART NO. | DESCRIPTION | COST |
| 1 | - | PRAXR FLUID | |
| 1 | - | CHAMBER | |
| 1 | - | FAVIO 4 | 5.00 |
| 1 | - | BRACK CURRY | |
| 1 | - | SHOP | 13.00 |

| CUSTOMER ESTIMATE | |
|-------------------|-------------|
| ESTIMATE AMOUNT | PARTS LABOR |
| ADD'L. AUTH. AMT. | TIME BY |
| ADD'L. AUTH. AMT. | |
| ADD'L. AUTH. AMT. | |
| ESTIMATE TOTAL | |

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, theft, accident or any other cause beyond your control.

WORK AUTHORIZED BY **X**

| | | | |
|------------------------------|---------------------|--------------|--|
| NAME | DATE | A.M. | P.M. |
| ADDRESS | 1/23/12 | | |
| CITY | ORDER WRITTEN BY | | |
| YEAR, MAKE AND MODEL OF AUTO | PH | | |
| MILEAGE | SERIAL NO. | ENGINE NO. | YES <input type="checkbox"/> NO <input type="checkbox"/> |
| 83338 | 637 BIRD | | |
| LICENSE NUMBER | TERMS | RETAIN PARTS | DESTROY PARTS |
| 620 FDB | | | |
| OPER NO. | DESCRIPTION OF WORK | | |

| | |
|----------------------------------|--|
| 1. LAMP ON BRAKES R4R RR | |
| WHEEL CYL 4 BLARD | |
| ADJUST ALL 4 BRAKES. | |
| 10 LBS POOR - R4R CARB RE-DORE | |
| 10 LBS AIR BLEEDS 4 MOTOR CARB - | |
| (MUCH BETTER) NORMAL ADJUST - | |
| MIGHT IS NOW POSSIBLE. | |

| TOTALS | |
|-----------------|--------|
| TOTAL LABOR | 165.00 |
| TOTAL PARTS | 18.00 |
| ACCESSORIES | |
| OUTSIDE REPAIRS | |
| TOTAL | |
| TAX | 1.29 |
| TOTAL AMOUNT | 184.29 |







Item



1 of 5

1



A/C Compressor-New Compressor 4 Seasons 58056



Quality Plus Parts (53004)

95.1% positive feedback



\$242.98



Order details



Time placed May 25, 2024 at 8:55 AM
Order number
Total \$253.52 (1 item)
Sold by qualityplusparts

Delivery info

Delivered on Thu, May 30, 2024



Paid
May 25




Tracking
available
May 25



Delivered
May 30

Item info




A/C Compressor-New
Compressor 4 Seasons 58...

✓ Fits your **1963 Ford
Thunderbird**

\$229.95

Return window closed on Jun
29, 2024.



CONCOURS PARTS & ACCESSORIES
3655 ARROWHEAD DR
CARSON CITY, NV 89706

Orders (800) 722-0009
Phone (775) 882-5100
Fax (775) 882-2404
Website www.concoursparts.com

Date: 09/25/2023 03:59:15 PM

Credit Card Order Confirmation

| | |
|---|---------------------------------|
| BILL TO: | SHIP TO: |
| IRA SCHWARTZ 3846 YOUNG WOLF DRIVE SIMI VALLEY, CA 93065 USA | [REDACTED] BURBANK, CA 91504 |
| Phone: 818-841-6959 | Phone: [REDACTED] |
| Fax: | Fax: |
| Email: [REDACTED] | |
| Account: [REDACTED] | Ordered by: IRA SCHWARTZ |
| Vehicle Information | |
| YEAR: 1963, MAKE: Ford, MODEL: Thunderbird, ENGINE SIZE: 390, BODY: Coupe, Auto Trans: Yes, Power Steering: Yes, Power Brakes: Yes, | |
| Comments: | |

YES

SPECIAL SHIPPING INSTRUCTIONS:

| Part # | Description | Style | Pkg | Year Range | Price | Qty Ordered | Extended Price | Core Charge |
|-----------------|---|-------|------|------------|-------|-------------|----------------|-------------|
| C3AZ-17618 | WINDSHIELD WASHER RESERVOIR-RED BAG W/ FOMOCO & OUTLET AT BOTTOM | | EACH | 1961-1963 | 30.00 | 1 | 30.00 | 0.00 |
| B8S-17632-A | WINDSHIELD WASHER RESERVOIR CAP-USED ON RESERVOIR WITH OUTLET AT BOTTOM | | EACH | 1958-1965 | 5.00 | 1 | 5.00 | 0.00 |
| 237A23-MR | DOOR PANEL ALUMINUM-LH - COUPE -W/ PWR WIN W/ REMOTE MIRROR | | EACH | 1963 | 95.00 | 1 | 95.00 | 0.00 |
| C3MY-6221999-CC | DOOR LOCK KNOB GROMMET-CHROME FINISH | | EACH | 1963-1964 | 8.00 | 2 | 16.00 | 0.00 |
| 06010-B | GLOVE BOX-ABS PLASTIC | | EACH | 1961-1963 | 49.95 | 1 | 49.95 | 0.00 |
| 8620-A | FAN TO A/C BELT-390 | | EACH | 1961-1962 | 15.50 | 1 | 15.50 | 0.00 |
| 17B719 | REMOTE MIRROR CONTROL BEZEL NUT | | EACH | 1963 | 13.95 | 1 | 13.95 | 0.00 |
| DF43-K | DECAL KIT-SET OF 13 | | SET | 1963 | 25.95 | 1 | 25.95 | 0.00 |
| DF164 | ENGINE COMPARTMENT DECAL-OIL CAP DECAL | | EACH | 1960-1965 | 7.50 | 1 | 7.50 | 0.00 |
| DF170 | INTERIOR DECAL-SUN VISOR STARTING INSTRUCTIONS | | EACH | 1963-1966 | 7.50 | 1 | 7.50 | 0.00 |
| 9030-G46 | FUEL CAP-REPLACEMENT | | EACH | 1961-1966 | 7.95 | 1 | 7.95 | 0.00 |
| C1AZ-17664-CR | WINDSHIELD WASHER PUMP | | EACH | 1961-1967 | 37.50 | 1 | 37.50 | 0.00 |
| 42514-A | TRUNK LID ORNAMENT PLASTIC INSERT | | EACH | 1961- | 19.95 | 1 | 19.95 | 0.00 |

1 of 2

| | | | | | | | |
|------------|---|--|------|-----------|-------|---|------------|
| | | | 1963 | | | | |
| | PLASTIC HOOD ORNAMENT | | EACH | 1961-1963 | 26.95 | 1 | 26.95 0.00 |
| | HOOD INSULATOR-5 PCS | | SET | 1961-1963 | 42.50 | 1 | 42.50 0.00 |
| 769- | COWL TO HOOD BUMPER | | EACH | 1958-1960 | 4.95 | 2 | 9.90 0.00 |
| 22-B | THUNDERBIRD NAME PLATE | | EACH | 1963-1964 | 34.95 | 1 | 34.95 0.00 |
| 9654-AR | AIR CLEANER TO CARBURETOR GASKET-BEFORE 2/24/64 - EXCEPT 3-2V | | EACH | 1958-1964 | 2.35 | 1 | 2.35 0.00 |
| C1SZ-27986 | FENDER SKIRT SEAL-DIE CUT | | PAIR | 1961-1963 | 24.95 | 1 | 24.95 0.00 |
| 30320-B | DOOR OR WINDOW HANDLE ESCUTCHEON | | EACH | 1961-1962 | 12.50 | 2 | 25.00 0.00 |
| L22-F | WIRING DIAGRAM-COMPLETE GUIDE TO WIRING IN COLOR | | EACH | 1963 | 10.95 | 1 | 10.95 0.00 |

| | | | | | | | |
|---------------------------------|--|--|--|--|--|----------|--|
| Total Merchandise | | | | | | \$509.30 | |
| Estimated Shipping & Handling | | | | | | \$45.00 | |
| Special Handling, Crating, etc. | | | | | | \$0.00 | |
| Sales Tax | | | | | | \$0.00 | |
| Core Charges | | | | | | \$0.00 | |
| | | | | | | | |
| Total Charges | | | | | | \$554.30 | |

INSTRUCTIONS:

| Part No. | Description | Qty | Unit Price | Ext Price | Core Charge |
|----------------|---|--------|------------|-----------|-------------|
| C742-2006 | WINDSHIELD WIPER REGULAR ON RED BAG W/ FORD LOGO & KIT SET AT BOTTOM | EACH | 1963 | 10.00 | 5.00 0.00 |
| ESS-17500-A | WINDSHIELD WASHER REGULAR ON CAP W/ REG ON WASHNOSE WITH OUTLET AT BOTTOM | EACH | 1963 | 5.00 | 5.00 0.00 |
| 237A35-000 | DOOR PANEL ALUMINUM-LH - COUPE - W/ PWR WIN W/ REMOTE MIRROR | EACH | 1962 | 95.00 | 95.00 0.00 |
| C1M-3021269-01 | DOOR LOCK TUBS GROMMET CHROME FINISH | EACH | 1964 | 9.50 | 18.50 0.00 |
| 94010-0 | DOOR BOX ABS PLASTIC | EACH | 1961-1963 | 43.95 | 43.95 0.00 |
| 5020-A | FLAT TO A/C BELT-36 | EACH | 1962 | 15.50 | 15.50 0.00 |
| 8767-19 | FRONT AIR FILTER CONTROL BOX KIT | 1/2 CH | 1962 | 13.95 | 13.95 0.00 |
| DF41-K | DOOR KIT SET OF 4 | SET | 1962 | 26.95 | 26.95 0.00 |
| DF41 | DOOR KIT SET OF 4 | EACH | 1962 | 7.00 | 7.00 0.00 |
| 21170 | INTERIOR DECOR - SUN VISOR MOUNTING INSTRUCTIONS | EACH | 1962 | 7.50 | 7.50 0.00 |
| 503-045 | FUEL CRAWPLACEMENT | EACH | 1962 | 7.50 | 7.50 0.00 |
| C162-172407 | WINDSHIELD WASH PUMP | EACH | 1961 | 37.50 | 37.50 0.00 |
| 94010-0 | DOOR BOX ABS PLASTIC | EACH | 1961 | 12.95 | 12.95 0.00 |

TYERMAN'S AUTOMOTIVE & SUSPENSION

Page 1

BAR #: 240797

Invoice No.

Order Date 06/22/23 10:22 am

1420 W.MAGNOLIA BLVD

000051971

Completed: 06/22/23 02:36 pm

BURBANK, CA 91506

Phone: 818 846-7291 FAX: 818 846-4675

Problem solvers for over 55 years.

[REDACTED]
BURBANK CA 91504
Home Phone: [REDACTED]
Work Phone: [REDACTED]

63 FORD THUNDERBIRD

84392 Mi.

Lic: 9FHL118/CA V8Cyl 6.4

Vin:

Eq:

Quotes

1 06/22/23 02:42pm 125.00

in person.

WHEEL IS AT THE 1 CLOCK POSITION. THE VEHICLE WANTS TO PULL TO THE LEFT.

Job01 ALIGNMENT CAR**Labor: \$125.00****Parts:**

ALIGN FRONT END, CHECK SUSPENSION

THE CASTER WAS VERY OFFSET

THE CASTER IS SET EVEN AT -2.5. WE CAN NOT GET IT ANY BETTER AND KEEP THE CASTER EVEN

THE CAMBER IS -0.25 ON BOTH SIDES

Status: Completed Tech: VALENTE

Job Subtotal: \$125.00**Recommendations:** HAS A STRONG BRAKE PULL TO THE LEFT

All parts are new unless stated.

Payments to TYERMAN'S AUTOMOTIVE & SUSPENSION Cost Summary

Status: Completed Work Order

Payments:

| | |
|----------|----------|
| Labor | 125.00 |
| Parts | 0.00 |
| Total | \$125.00 |
| Payments | 0.00 |
| Bal Due | 125.00 |

Thank you for choosing TYERMAN'S AUTOMOTIVE & SUSPENSION



Order details



Time placed Oct 11, 2024 at 7:43 AM
Order number
Total \$284.16 (1 item)
Sold by [denniscarpenterrestorationparts](#)

Delivery info

Delivered on Fri, Oct 18, 2024



Paid
Oct 11




Tracking
available
Oct 14



Delivered
Oct 18

Item info



Roof Rail Seals Hardtop
1961-63 Ford Thunderbird...

\$264.95

Returns accepted through
Nov 17, 2024.

ACCUFORMPLASTICS

October 17, 2023

SHIP TO




Burbank CA 91504
United States

BILL TO

Simi Valley CA 93065
United States

ITEMS

QUANTITY

| | | |
|---|---|--------|
|  | ACCUFORM® 4015L Door Panel Cover Fits 62-63 Thunderbird 4015L | 1 of 1 |
|  | ACCUFORM® 4015R Door Panel Cover Fits 62-63 Thunderbird 4015R | 1 of 1 |
|  | ACCUFORM® 448 Dashboard Cover Fits 62-63 Thunderbird 448 | 1 of 1 |

Thank you for shopping with us!

accuformplastics

3023 Old farm Road, Washington UT 84780, United States
accuformplastics@gmail.com
accuformplastics.com