

VMC PRE-SALE VEHICLE INSPECTION FORM

Inspector CA

Stock # 2260215

Make Ferrari

Mileage 13068

Year 2011

Model 458 Italia

Date 2/19/26

TEST DRIVE

Starting Pass Brakes (Incl Parking) Pass

Shocks Pass

Guages Pass Engine Performance Pass

Heater Pass

Exhaust Leaks Pass Air Conditioning Pass

Clutch Pass

Steering Pass Transmission Pass

Squeak/Rattles Pass

Vibrations Pass Leaks Pass

Wipers Pass

ON LIFT

Fluid Levels Pass Exhaust Condition Pass

Suspension Pass

Frame Pass Floor Pans Pass

Trunk Pan Pass

Inner Panels Pass Gas Tank Pass

Tires 2024 Pass

Leaks Pass U-Joints Pass

Belts Pass

ON FLOOR

Paint Small chip on door handle Glass Pass

Plating Pass

Metal Pass Door Operation Pass

Hood Operation Pass

Trunk Pass Panel Gaps Pass

Window Oper. Pass

Top Operation N/A Mirrors Pass

Shades Pass

Seat Operation Pass Radio Pass

Lights Pass

Turn Signals Pass Brake Lights Pass

Backup Light(s) Pass


Interior Lights Pass Dash Lights Pass

Glove Box Pass

Spare N/A Coolant Pass

Horn Pass

Damage



Notes

1. Small Chip in paint on Passenger Door Handle.
