

VMC PRE-SALE VEHICLE INSPECTION FORM

Inspector CA

Stock # 2260216

Make Bentley

Mileage 23933

Year 2015

Model Continental GTC W12

Date 2/24/26

TEST DRIVE

Starting Pass Brakes (Incl Parking) Pass

Shocks Pass

Guages Pass Engine Performance Pass

Heater Pass

Exhaust Leaks Pass Air Conditioning Pass

Clutch Pass

Steering Pass Transmission Pass

Squeak/Rattles Pass

Vibrations Pass Leaks Pass

Wipers Pass

ON LIFT

Fluid Levels Pass Exhaust Condition Pass

Suspension Pass

Frame Pass Floor Pans Pass

Trunk Pan Pass

Inner Panels Pass Gas Tank Pass

Tires 2024 Pass

Leaks Pass U-Joints Pass

Belts Pass

ON FLOOR

Paint Small chip on door handle Glass Pass

Plating Pass

Metal Pass Door Operation Pass

Hood Operation Pass

Trunk Pass Panel Gaps Pass

Window Oper. Pass

Top Operation Pass Mirrors Pass

Shades Pass

Seat Operation Pass Radio Pass

Lights Pass

Turn Signals Pass Brake Lights Pass

Backup Light(s) Pass

Interior Lights (1) map light out. Dash Lights Pass

Glove Box Pass

Spare

Pass


Coolant

Pass

Horn

Pass

Damage



Notes

1. Bumper shows stress cracks below paint. | 2. Slight deformation in door panel.

Disclaimer: VMC Pre-Sale Inspection is for internal use only and does not certify condition. Customers are advised to perform their own inspections prior to purchase.